

To: Sorrenson - DNR, Allen[allen.sorenson@state.co.us]
From: Way, Steven
Sent: Mon 3/24/2014 10:45:40 PM
Subject: FW: Gold King Rehab Phase I
Gold King Phase 1.pdf

FYI – second set

Federal On-Scene Coordinator

Emergency Response Program (8EPR-ER)
US EPA Region 8
1595 Wynkoop Street
Denver, CO 80202-1129

Office: 303-312-6723

From: Todd Hennis [mailto:[Personal Email/Ex. 6](#)]
Sent: Monday, March 17, 2014 2:04 PM
To: Way, Steven
Subject: Fw: Gold King Rehab Phase I

Steve-

Phase 1 (the actual portal) estimate for Gold King. This is assuming the excavation of 70 feet into the mountain to get to good rock to anchor the portal, and then having to place 70 feet of the steel sets. In actuality, I would be surprised if this goes to more than 40 feet of sets. The mountain will get excavated back, but not the entire length will get steel sets (i.e. there will be an indentation in the mountain at the portal). The dirt and rock is assumed to go on the dump as additional cover.

For San Juan corp.,

Todd C. Hennis, Pres.

On Monday, March 17, 2014 1:37 PM, Pete Maisel <pmaisel@thebent.com> wrote:

Pete Maisel

Maisel Excavation,LLC

www.maiselx.com

pete@maiselx.com

970.759.9291

This email is free from viruses and malware because avast! Antivirus protection is active.